


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-078	Smoke	9/10/2008	ADS/TM	S13AA1020MH	Dry	Yes	696.48



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-078	Smoke	9/10/2008	ADS/TM	S13AA1020MH	Dry	Yes	696.48

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13AA1020G1	S13AA1020MH	S13AA1025MH	118.5738	8
S13AA1034G1	S13AA1034DE	S13AA1009MH	89.00453	8
S13AA1024G1	S13AA1024MH	S13AA1020MH	205.4242	8
S13AA1015G1	S13AA1015MH	S13AA1020MH	264.3373	8
S13AA1009G1	S13AA1009MH	S13AA1024MH	19.13542	8

Observations & Photos

Obs_ID S1028-078-OB01

Address 2910 Violet Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S13AA1024MH

Comments Smoke from cleanout in back yard. 2910 Violet Ave.



Picture \S1028-078-OB01-P01.jpg

Comments Back of house, 2910 Violet Ave.

Obs_ID S1028-078-OB02

Address 2916 Violet Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S13AA1024MH

Comments Smoke from cleanout in back yard. 2916 Violet Ave.



Picture \S1028-078-OB02-P01.jpg

Comments Back of house, 2916 Violet Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-078	Smoke	9/10/2008	ADS/TM	S13AA1020MH	Dry	Yes	696.48

Obs_ID S1028-078-OB03

Address 2922 Violet Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S13AA1020MH

Comments Smoke from cleanout in back yard. 2922 Violet Ave.



Picture \S1028-078-OB03-P01.jpg

Comments Back of house, 2922 Violet Ave.

Obs_ID S1028-078-OB04

Address 3707 Overview Rd


Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA1020MH

Comments Smoke from cleanout in front yard. 3707 Overview Rd.



Picture \S1028-078-OB04-P01.jpg

Comments Front of house, 3707 Overview Rd.
